

# FORD® TRITON SPARK PLUG PORCELAIN EXTRACTOR KIT

Product # H3659 | Model #



- Designed to extract frozen or broken porcelain part of the spark plug in the 3 Valve Ford Triton engines. 2004 to present
- Using these special tools and a strong epoxy you should be able to extract the broken porcelain left behind when spark plug removal was attempted
- The advantage of this method of extraction is to prevent broken pieces of porcelain from entering the combustion chamber
- Ford specifically does NOT recommend pushing the broken porcelain down into the cylinder Doing so would mean the removal of the cylinder head
- Kit Contains: